



Обозначение	R	L	h=h1, мм	b, мм	f, мм	l1, мм	
CKJNR/L 2525 M 16	2	-	25	25	32	150	1604