



Обозначение	R	L	h=h1, MM	b, MM	f, MM	l1, MM	
DCLNR/L 2525 M 12	5	2	25	25	32	150	1204